Work Orde	er ID 51455 8:02:04 AM										Page 1
	D2656-15 D Wearshoe		Accept				iiii s	Setup	Start Stop	*	
Start Date: Required Date: Reference:	08/24/09 Start Qty: 08/31/09 Req'd Qty: 08/31/09 Return 2009/RA109077/R0	6.00		Cust Item I Customer:	ID:						
Approvals:	Process Plan:	Date:	Tooling:	Date:		F	Run	Start Stop			
Sequence ID/ Work Center II	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr										
D2656	Rev D			•							1
190 QC	QC5- Inspect pa	ert completeness to step on W	O.00				6				65.08.24
Quality Control		6 of original D2656-15 B439	991 Rev.D. All parts in good co	endition for re-							/
200	Pick Kit		0.00				<u>چ</u>				2/1/28
Packaging	Me	mo	0.00	`				• —			111-0
Packaging	Pict	k B43991 from Return 2009 l	RA109077/R09-077.								
	4	aceiust stock,	linventury by L. L	or M.F.X		>					
210		wg & Stock Location:									
Packaging	Me		0.00				Committee and the first designation of the fir	-			- Automobility
Packaging	Ret	urn to stock with the new bat	ch #,								•

## Work Order ID 51455

Page 2

August 25, 2009 8:02:04 AM

D2656-15

D

**Revision ID:** 

Item Name: Wearshoe

**Start Date:** Required Date: 08/31/09

08/24/09 Start Qty: 6.00 Req'd Qty: 6.00

Return 2009/RA109077/R09-077

Reference:

Approvals: Process Plan:

Operation

Description

Date:

Date:\_\_\_\_\_ SPC (Y/N):

Set Up/

QC21- Final Inspection - Work Order Release

Memo

0.00

**Run Hours** 

Tooling:

0.00

Stop



Run Start

Stop

Reject

Qty

09608/26/56/56 pl 09-8-26 (C)

Accept

Qty

Item ID:

Accept

Date:

Date:

Draw

Rev.

**Cust Item ID:** 

Draw

Number

Setup Start

**Customer:** 

Plan

Code

Reject

Number

Insp. Stamp

220



Sequence ID/

Work Center ID

Quality Control

August 25, 2009 8:02:03 AM

Work Order ID: 51455

Parent Item:

Comments:

D2656-15RevD

Parent Item Name:

Wearshoe



Start Date: 08/24/09

Required Date: 08/31/09

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name

Item ID

Replacement Mfg/ Purch

Primary Bin Item Location Last Location Route Seq ID

Unit of Measure Hand

Qty on

Remaining Qty Qty To Pick Issued

Date Issued

Status

D2656-13RevD

Manufactured

No

Each

10.0000


6.0000

14/126

Wearplate

Warehouse	Loc Oty	Loc Code				
Location						
Main Warehouse						
ST	10					
20755	0					
44158	10					

fetern 2009 D2656-15 B43991



Copyright © 1997 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.